

**FORD:**

2001-2005 Escape  
2005 Escape Hybrid

**MERCURY:**

2005 Mariner

**ISSUE**

Some 2001-2005 Escape, 2005 Escape Hybrid and Mariners may exhibit squeaks from the shedlip seal for the doors. This seal runs along the top edge of the doors, above the top section of the individual door inner seals. This is most likely to be noticed at slow speeds and when the body is put into a twist.

**ACTION**

Replace the seals.

PART NUMBER	PART NAME
5L8Z-7851222-AA	Shedlip Seal (2 per repair)

**WARRANTY STATUS:** Eligible Under Provisions Of  
New Vehicle Limited  
Warranty Coverage

OPERATION	DESCRIPTION	TIME
052211A	2001-2005 Escape, 2005 Escape Hybrid, 2005 Mariner: Replace The Shedlip Seal For Both Doors	0.2 Hr.

**DEALER CODING**

BASIC PART NO.  
7851222

**OASIS CODES:** 110000, 702000

CONDITION  
CODE  
41

**NOTE:** The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.