

HONDA Service Bulletin



Applies To: 2006 Civic 4-Door - ALL

2006 Civic Hybrid – ALL

2007 Civic 4-Door - From VIN JHMFA1...7S000001 thru JHMFA1...7S008716 2007 Civic Hybrid - From VIN JHMFA3...7S000001 thru JHMFA3...7S021364

September 7, 2007

Front Door Glass Comes Out of the Channel

(Supersedes 06-014, dated July 20, 2007, to update the information marked by the black bars)

SYMPTOM

The glass in the driver's or front passenger's door comes out of the run channel, or it binds and then stalls when you try to close the window.

PROBABLE CAUSE

The manufacturing tolerances are not within specification for the glass run channel, the door glass, and the window regulator.

CORRECTIVE ACTION

Replace the glass run channel, the door glass, and the window regulator.

PARTS INFORMATION

Front Glass Run Channel:

Driver's side -

P/N 72275-SNA-A01, H/C 8053498

Passenger's side -

P/N 72235-SNA-A01, H/C 8053449

Front Window Regulator:

Driver's side -

P/N 72250-SNA-A02, H/C 8608689

Passenger's side -

P/N 72210-SNA-A02, H/C 8608671

Front Door Glass:

Driver's side -

P/N 73350-SNA-A12, H/C 8608739

(EX, LX, and Hybrid models)

P/N 73350-SNA-A02, H/C 8608713 (DX model)

Passenger's side -

P/N 73300-SNA-A12, H/C 8608721

(EX, LX, and Hybrid models)

P/N 73300-SNA-A02, H/C 8608705 (DX model)

REQUIRED MATERIALS

Shin Etsu Silicone Grease:

P/N 08798-9013, H/C 4642294

One tube repairs about 20 vehicles.

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

OP#	Description	FRT
8261A0	Replace the driver's door glass and the window regulator.	0.8
8261A0A	Replace the driver's door glass run channel.	0.3
8271A0	Replace the front passenger's door glass and the window regulator.	0.8
8271A0A	Replace the front passenger's door glass run channel.	0.3

Failed Part: P/N 72275-SNA-A11

H/C 8303257

Defect Code: 03001 Symptom Code: 08202

Skill Level: Repair Technician

Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Parts and Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

REPAIR PROCEDURE

- 1. Remove the appropriate front inner door panel:
 - Refer to page 20-9 of the 2006–2007 Civic Service Manual, or
 - Online, enter keyword PANEL REM, then select Front Door Panel Removal/Installation (4-door) from the list.
- 2. Remove the door glass:
 - Refer to page 20-19 of the service manual, or
 - Online, enter keyword DOOR GLASS, then select Front Door Glass and Regulator Replacement from the list.

© 2007 American Honda Motor Co., Inc. - All Rights Reserved

ATB 32127-37883 (0709)

1 of 2



3. Replace the glass run channel. Lightly coat the inside of the glass run channel with Shin Etsu silicone grease.



- 4. Replace the window regulator and the door glass with new parts:
 - Refer to page 20-19 of the service manual, or
 - Online, enter keyword DOOR GLASS, then select Front Door Glass and Regulator Replacement from the list.
- 5. Adjust the window to make sure the glass is pushed to the back of the door, then tighten the glass mounting bolts:
 - Refer to page 20-35 of the service manual, or
 - Online, enter keyword GLASS ADJUST, then select Glass Adjustment from the list.
- 6. Reassemble the remaining parts in the reverse order of removal.
- 7. Do the power window control unit reset procedure:
 - Refer to page 22-225 of the service manual, or
 - Online, enter keyword RESET, then select Power Window Control Unit Reset from the

2 of 2 06-014